

12201 O'DONNELL ST.



**BUILDING AND STANDARDS BOARD AGENDA ITEM #8 FOR
WEDNESDAY, APRIL 30, 2014**

**ENVIRONMENTAL SERVICES DEPARTMENT
CODE COMPLIANCE DIVISION**

**MEMORANDUM
MARCH 16, 2014**

TO: The Honorable Chairman and Board Members

THROUGH: Elda Rodriguez-Hefner, Division Manager, Code Compliance Department

FROM: Ron Roth, C.B.O., Deputy Building Official

SUBJECT: 12201 O'Donnell Street, El Paso, Texas, 79934-2212

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on October 05, 2013. This single family mobile home was built in 1978, constructed on a metal chassis with wood framed walls and roof. The exterior walls finish consists of wood siding. The interior walls and ceilings finish consists in gypsum board. The structure was found accessible to vagrants and extensively damaged by fire which occurred on or about April 12, 2013. There are weeds, trash, and debris throughout the property.
- 2) A certified condemnation letter was mailed to Kendall Clarence & Heike M.
- 3) Certified notices of the public hearing scheduled for April 30, 2014 were mailed to the owners and all interested parties on April 15, 2014.
- 4) As of April 10, 2014, \$97.54 is owed in taxes.

The owner has been notified of the property violations at this property, to date there has been no response or corrective action taken, and therefore the department recommends that it be found:

- 1) That the structures are substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structures are not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structures' certificate of occupancy remain revoked; and
- 4) That the structures cannot be rehabilitated; and
- 5) That the garage, accessory structure and the rear dwelling structure be demolished within thirty (30) days; and
- 6) That the premises be cleaned and maintained clean of all weeds, trash, and debris within thirty (30) days; and
- 7) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Code Compliance Division
MARCH 3, 2014
NOTICE OF VIOLATION

KENDALL CLARENCE & HEIKE M
12201 O'DONNELL ST
EL PASO, TX 79934-2212

Re: 12201 O'DONNELL ST
Blk: 1 FUTURE LAND
Lot: 10
Zoned: R - F
Case Number ENHS14-00343
91 7199 9991 7030 7756 1718

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at 12201 O'DONNELL ST. EL PASO, TX 79934 is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]

- o. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec. 603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1, 604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 599-6290 or 240-2273.

Alexandro Esparza
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

LOCATION: City Hall, City Council Chambers, 300 N. Campbell Street, 1st Floor, El Paso, Texas 79901

DATE: April 30, 2014

TIME: 5:30 p.m.

PROPERTY: 12201 O'Donnell St., El Paso, Texas also described as Lot 10, Block 1, FUTURE LAND UNIT ONE, an addition to the City of El Paso, El Paso County, Texas, according to the plat thereof recorded in Volume 1, Page 40, Plat Records of El Paso County, Texas.

The property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, **Clarence Kendall & Heike Monika Kendall, 12201 O'Donnell St., El Paso, Texas, 79934**, are the owners, herein after referred to as the “Owners” of the Property. If you no longer own or have an interest in the Property, you must execute an affidavit stating that you no longer own or have an interest in the Property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the Property, even if you do not.

On or about October 5, 2013, an inspection of the property was conducted by the Environmental Services Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1

conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]

- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec.502.1, 502.2, 502.3, 502.4, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage system. [Sec. 506.1, 506.2, 506.3]
- o. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]

- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1, 604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

The Owners are entitled to show cause that the Property is safe, does not constitute dangerous structures and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the Owners advocate for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the Property is safe or that it can be repaired, must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the Owners fail to comply with the order of the Commission the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the final order. The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. The bylaws may be obtained at the Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907 or by calling (915) 599-6290.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNERS AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the Property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

Wendi N. Vineyard
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice of Public Hearing regarding the property located at **12201 O'Donnell St.** was filed with the County Clerk's Office, the official public records of real property for El Paso County.

Richarda Duffy Momsen

Executed this ____ day of _____, 2014 on behalf of the City of El Paso, Texas, by Richarda Duffy Momsen in her capacity as City Clerk.

STATE OF TEXAS
COUNTY OF EL PASO

Subscribed and sworn to before me, this ____ day of _____, 2014.

Notary Public

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at **12201 O'Donnell St.** was PUBLISHED in the official City newspaper on the ____ day of _____, 2014.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at **12201 O'Donnell St.** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Clarence Kendall & Heike Monika Kendall
12201 O'Donnell St.
El Paso, Texas 79934

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **12201 O'Donnell St.** was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, TX 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **12201 O'Donnell St.** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at
12201 O'Donnell St. was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at
12201 O'Donnell St. was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Clerk, Probate Dept.
500 E. San Antonio Avenue, Suite 105
El Paso, Texas 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at
12201 O'Donnell St. was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas Suite 1400
El Paso, TX 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at
12201 O'Donnell St. El Paso, Texas.

Date: _____

Time: _____

Inspector: _____



UNSAFE STRUCTURES REPORT

CODE COMPLIANCE DIVISION

DATE OF EXAMINATION: April 04, 2014

REP. DISTRICT: 4

ADDRESS: 12201 O'Donnell Street

ZONED: R-F

LEGAL DESCRIPTION: Lot 10, Block 1, Future Land

OWNER: Kendall Clarence & Heike M.

ADDRESS: 12201 O'Donnell Street
El Paso, TX 79934-2212

BUILDING USE: Abandoned, Fire Consumed, Single-Family Mobile Home

TYPE OF CONSTRUCTION: V, wood framing on metal chassis.

FOOTINGS: N/A

CONDITION: N/A

FOUNDATION WALL: N/A

CONDITION: N/A

FLOOR STRUCTURE: Metal framing system with wood composite sheathing.

CONDITION: Poor, fire damaged. A structural engineer should be hired to evaluate actual condition.

EXTERIOR WALLS: Wood framing with siding covering.

HEIGHT: 8' - 10' +/-

THICKNESS: 4" +/-

CONDITION: Poor, fire damaged. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

INTERIOR WALLS & CEILINGS: Wood framing w / gypsum board covering

CONDITION: Poor fire damaged. Interior walls and ceilings have been vandalized and are water damaged due to exposure to the elements. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

ROOF STRUCTURE: Wood frame with metal roof covering.

CONDITION: Poor, fire damaged. A registered roofing contractor licensed in the state of Texas must be hired to evaluate the roofing system and submit a report of required corrections to bring the roof system into compliance.

DOORS, WINDOWS, ETC.: Wood frame doors and aluminum frame windows.

CONDITION: Poor, fire damaged. Several windows and doors are broken. Will need to replace or repair doors and windows, so they are operational and meet egress requirements.

MEANS OF EGRESS: Does not meet code requirements.

CONDITION: Poor. Windows and doors must be replaced to make them operational.

PLUMBING: Fire damaged fixtures. A licensed plumber should be hired to bring system up to code.

ELECTRICAL: Fire damaged conductors and fixtures. A licensed electrician should be hired to bring system up to code.

MECHANICAL: Fire damaged equipment. A licensed mechanical contractor should be hired to bring system up to code.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: 0

WARNING POSTED: Yes

BARRICADED: No

POLICE AID REQD.: No

REMARKS: This single family mobile home was built on or about 1978 and found fire damaged and abandoned and in a state of disrepair. The mobile home has been severely damaged by a fire that occurred on or about April 12, 2013 and poses potential danger to unauthorized occupants. The middle section of the mobile home has been totally consumed by the fire exposing the remaining structure to the elements. The structure should be demolished within thirty (30) days. The premises should be cleaned of all weeds, trash and debris within thirty (30) days and be maintained clean of all weeds, trash and debris.

Alexandro Esparza

Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

ORACLE

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR
ACT8006 v1.242 04/10/2014 10:04:
ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. Roll Code

Certified Owner

Parcel Address

Amount Due as of CAD No.

Tax Units

Tax Unit Description

List of Tax Units

☐ Countywide

Tax Unit, Yr, Rec. Type

Tax Unit

Year

Rec. Type

Amount Due/Paid Information

Year	Gross Value	H	O	V	D	Excodes	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2013	\$27,024	Y			Y	Excodes	\$87.88	\$0.00	\$0.00	\$87.88	\$9.66	\$0.00	\$97.54
2012	\$27,024	Y			Y	Excodes	\$79.68	\$79.68	\$0.00	\$0.00	\$5.58	\$0.00	\$0.00
2011	\$27,287	Y			Y	Excodes	\$80.71	\$80.71	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2010	\$27,551	Y			Y	Excodes	\$78.29	\$78.29	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2009	\$27,814	Y			Y	Excodes	\$78.24	\$78.24	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2008	\$29,011	Y			Y	Excodes	\$86.71	\$86.71	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2007	\$29,011	Y			Y	Excodes	\$85.72	\$85.72	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2006	\$29,011	Y			Y	Excodes	\$92.66	\$92.66	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2005	\$30,802	Y			Y	Excodes	\$220.44	\$220.44	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Totals							\$2,867.40	\$2,779.52	\$0.00	\$87.88	\$15.24	\$0.00	\$97.54

Last Payment Date

Last Payer

9:04 AM
4/10/2014